


## \* INDICATION LAMP COLOR STATUS

NO		MODE							
	GREEN	RED	WIODE						
1	Steady	_	Full charged						
2	N	Steady	Charging						
3		- 4	Discharging						
4	-	1-1	Battery fault						



- 1. After LIGHITNG is installed, please connect red line of battery into BAT (+) (Red)
- 2. When the continuous power is not supplied, red line of battery into BAT (+) (Red) should be disconnected to avoid natural discharge of battery.
- 3. Please install switch for on/off LIGHTING.

TITLE: LEB125WS-0550UWNM2GLw17BuQC50	SCALE	N/S	UNIT	ММ	NO.	REVISED
0 1: 0:					$\triangle$	
Connection Diagram	PROJECT METHOD	⊕ ←	WEIGHT	KG	$\triangle$	
				NG.	Δ	
	APPROVED	B. K. KIM			MATERIAL	ASS'Y
<b>DAEYANG</b>	CHECKED				DWG NO.	
	DRAWN	B. I. KIM			44.4	
	DATE	2016.02.	02		Sheet No.	11-A

NO

◬

CONTENT

DATE

REVISER

APPROVAL